16.06 Principles of Automatic Control

Problem Set 6 Issued: October 12, 2011

Due: October 19, 2011

Instructions: Do each problem on separate sheets of paper, and staple the sheets for each problem together. Write your name on each problem.

Problem 1

Do Problem 5.25 from FPE.

Problem 2

Do Problem 5.28 from FPE.

Problem 3

Sketch the 0° locus for the examples given in FPE 5.7.

MIT OpenCourseWare http://ocw.mit.edu

16.06 Principles of Automatic Control Fall 2012

For information about citing these materials or our Terms of Use, visit: http://ocw.mit.edu/terms.